




All new seals – Ultrasonic cleaned



New oil pump shaft and seal fitted



Tuning chip never fitted

